


XTREME®







Instruction Manual model: 18022

MAX 60kg/132lbs VESA200x200/200x400/400x400/400x800mm


(A)	M6x55 x6	(C)	M8x25 x4	(E)	M6x30 x4	(G)	M5x30 x4	(I)	M4x30 x4	(K)	Ø 8 x6	(M)	M x4	(O)	M x2
(B)	Ø10x45 x6	(D)	M8x40 x4	(F)	M6x12 x4	(H)	M5x12 x4	(J)	M4x12 x4	(L)	M x4	(N)	M x4		




1




2




3-Flat Back TV with M4/M5 Machine Screws




3-Curved Back TV with M4/M5 Machine Screws




3-Recessed Back TV with M4/M5 Machine Screws




3-Flat Back TV with M6/M8 Machine Screws




3-Curved Back TV with M6/M8 Machine Screws




3-Recessed Back TV with M6/M8 Machine Screws



3



4



Tighten Safety Bolts